

Wayne Western - Re: Fwd: Red Chief Mine ML 50765*Incoming*

From: Wayne Western
To: Blake, John
Subject: Re: Fwd: Red Chief Mine ML 50765
CC: Paul Baker

*S/015/0083**Red Chief Mine*

John,

Paul Baker and I reviewed our email and our files. The Division concurred with your finding for total bond release on the Red Chief Mine.

The Division will send a letter to the Operator stating the Division concurred with bond release and closed the file.

Thanks for your help.

Wayne Western

>>> John Blake 3/16/2011 9:58 AM >>>

And the correct DOGM number is S/015/0083. (I was looking at the wrong file when I originally composed this Email)

>>> John Blake 3/16/2011 9:33 AM >>>

Wayne,

I visited this site, S/015/0094, on March 15, 2011. The operator regraded the original site, as requested, to obliterate the mining cut and spread the boulders around a bit. (I think the reclamation actually resulted in a greater surface disturbance than was originally present.) The restored drainages look fine. Reseeding should not be required because the original surface was barren rock outcrop. I am attaching some pictures of the reclamation that was performed. I suggest that DOGM close its file on this permit. I plan to release the \$2000 CD that SITLA is holding as a reclamation bond. Please let me know if you have any concerns. Thanks. JB

RECEIVED E-Mail

MAR 16 2011

Div. of Oil, Gas & Mining

Wayne Western - Fwd: Red Chief Mine ML 50765*Incoming*

From: John Blake
To: Wayne Western
Date: 3/16/2011 10:00 AM
Subject: Fwd: Red Chief Mine ML 50765
Attachments: Img_0327.jpg; Img_0328.jpg; Img_0329.jpg; Img_0330.jpg; Img_0331.jpg; Img_0332.jpg; Img_0333.jpg

*S/015/0083
Red Chief Mine*

And the correct DOGM number is S/015/0083. (I was looking at the wrong file when I originally composed this Email)

>>> John Blake 3/16/2011 9:33 AM >>>
Wayne,

I visited this site, S/015/0094, on March 15, 2011. The operator regraded the original site, as requested, to obliterate the mining cut and spread the boulders around a bit. (I think the reclamation actually resulted in a greater surface disturbance than was originally present.) The restored drainages look fine. Reseeding should not be required because the original surface was barren rock outcrop. I am attaching some pictures of the reclamation that was performed. I suggest that DOGM close its file on this permit. I plan to release the \$2000 CD that SITLA is holding as a reclamation bond. Please let me know if you have any concerns. Thanks. JB

RECEIVED E-Mail

MAR 16 2011

Div. of Oil, Gas & Mining